

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402450384

Date Received:
07/24/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10716

Name of Operator: ROCKY MOUNTAIN MIDSTREAM LLC

Address: ONE WILLIAMS CENTER

City: TULSA State: OK Zip: 74172

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Annette Garrigues

970-618-3329

annette.garrigues@williams.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697501649

Inspection Date: 06/08/2020

FIR Submit Date: 06/18/2020

FIR Status: _____

Inspected Operator Information:

Company Name: ROCKY MOUNTAIN MIDSTREAM LLC

Company Number: 10716

Address: ONE WILLIAMS CENTER

City: TULSA State: OK Zip: 74172

LOCATION - Location ID: _____

Location Name: _____ Number: _____ County: _____

Qtrqr: NWS Sec: 14 Twp: 5N Range: 65W Meridian: 6
W

Latitude: _____ Longitude: _____

FACILITY - API Number: 05-123- -00 Facility ID: 476934

Facility Name: To Be Determined Number: _____

Qtrqr: NWS Sec: 14 Twp: 5N Range: 65W Meridian: 6
W

Latitude: _____ Longitude: _____

CORRECTIVE ACTIONS:

1 CA# 139835

Corrective Action: Per Rule 313B.a., submit a Form 12 for this gas gathering system. Please update information using Facility ID #476934.

Date: 07/16/2020

Please contact Steve Wheeler with any questions.

Response: CA COMPLETED

Date of Completion: 07/16/2020

Operator
Comment: Completed

COGCC Decision: _____

COGCC
Representative:

--

2 CA# 139836

Corrective Action:

Comply with Rule 1003 to properly recontour and revegetate the section of line to allow for successful flood irrigation and import new topsoil (refer to Photos 4-5) that will be suitable for vegetative growth.

Date: 06/22/2020

Operator shall collaborate with the surface owner and perform the corrective actions. If temporary measures need to be performed before recontouring the section of line, then those temporary measures should be performed in collaboration with the surface owner.

Operator shall contact the surface owner no later than June 22, 2020 to collaborate and perform the corrective actions.

Refer to the COGCC Comments section for additional corrective actions and comments.

Response: CA COMPLETED

Date of Completion: 06/22/2020

Operator
Comment:

Rocky Mountain Midstream has been in communication with the landowner and ROW reclamation work is to be completed this fall.

COGCC Decision: _____

COGCC
Representative:

--

OPERATOR COMMENT AND SUBMITTAL

Comment: Will follow up again in the fall.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Annette Garrigues

Signed: _____

Title: Environmental Specialist

Date: 7/24/2020 9:48:20 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files