

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/11/2020

Submitted Date:

09/14/2020

Document Number:

690200640

**FIELD INSPECTION FORM**Loc ID 308859 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD State: CO Zip: 8111-

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Mack, Ronald		ronaldmack@tcenergyllc.com	
Fitzgerald, Edie		ediefitzgerald@tcenergyllc.com	
BAKER DAVID		dbaker@auroramp.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283710	WELL	PR	03/09/2006	GW	071-08734	GOLDEN EAGLE 20-3	RI

**General Comment:**

This is a stormwater management inspection.  
See attached photos and additional details within this report.

Operator is directed to perform corrective actions outlined on this inspection report immediately. This inspection is being entered for notification and documentation only and is not intended to provide the Operator the opportunity to resolve the alleged violations without the imposition of a penalty, pursuant to Rule 522.c.

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is erosion along the main access road. Stormwater is not properly diverted toward the culvert causing erosion of the road.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402488620	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246609">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246609</a>
690200641	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246603">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246603</a>