

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/19/2020

Submitted Date:

11/23/2020

Document Number:

696202043**FIELD INSPECTION FORM**Loc ID 412922 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10515Name of Operator: GUNNISON ENERGY LLCAddress: 1801 BROADWAY #1150City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		tyson.johnston@oxbow.com	
		heather.lang@oxbow.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412922	LOCATION	AC			-	DGU Federal 1289 17-11 Pad	RI

General Comment:

On 11/19/2020, Reclamation Specialist Trujillo conducted an interim reclamation and stormwater inspection at Gunnison Energy LLCs DGU Federal 1289 17-11 Pad location in Gunnison County, Colorado.

The following compliance issues were observed during this inspection:
§34-60-121(1)(a), C.R.S.: Form 4 condition requirements- Signage

Refer to the "Location" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type OTHER

Comment: Pursuant to conditions within the 502.b Delayed Interim Reclamation NTO document #401463219, Operator was required to post a sign at the location entrance stating the following: "A COGCC variance has been approved to delay the commencement of interim reclamation to no later than December 9, 2022".

It was observed in this inspection that signage with required information has not been installed at the Location entrance in a plainly visible manner, in accordance with Form 4 conditions.

Corrective Action: Comply with Form 4 #401463219 and post a sign at the location entrance stating the following: " A COGCC variance has been approved to delay the commencement of interim reclamation to no later than December 9, 2022". A CA date of 3/15/2019 is being provided as this was when the sundry variance and conditions were approved.

Date: 03/15/2019

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 412922 Type: LOCATION API Number: - Status: AC Insp. Status: RI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402538365	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5296313
696202044	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5296311