

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Pipe fencing		
Corrective Action:		Date:	

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Bradenhead	# 1	Bradenhead valve is exposed at surface.			
Plunger Lift	# 1				
Flow Line	# 1				
Deadman # & Marked	# 4	SW guy line anchor is not marked. See attached photo.	Install proper guy line markers per Rule 1003.a	02/19/2021	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:	Location #307053				
Corrective Action:				Date:	

Paint

Condition	
-----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 216920 Type: WELL API Number: 069-06107 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 2/2/2021 at approximately 14:00 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the Magpie Operating Haggarty-Warberg #1 location #307127 in Larimer County, Colorado. While there, I observed that the SW guy line anchor was unmarked. During this inspection the following possible compliance issues were observed: Rule 1003.a. with a corrective action date of 2/19/2021. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.</p>	petersont	02/02/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697002983	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5342988