

FORM  
6Rev  
11/20

## State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

402631800

Date Received:

## WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 76840

Contact Name: Jeff Schneider

Name of Operator: SCHNEIDER ENERGY SERVICES INC

Phone: (970) 867-9437

Address: P O BOX 889

Fax: (970) 867-9137

City: FORT MORGAN State: CO Zip: 80701

Email: jeff@schneiderenergy.com

**For "Intent" 24 hour notice required,**

Name: Petrie, Erica

Tel: (303) 726-3822

**COGCC contact:**

Email: erica.petrie@state.co.us

Type of Well Abandonment Report: ☒ Notice of Intent to Abandon ☐ Subsequent Report of Abandonment

API Number 05-123-05372-00

Well Name: APRIL

Well Number: 12-14

Location: QtrQtr: SWNW Section: 14 Township: 7N Range: 60W Meridian: 6

County: WELD

Federal, Indian or State Lease Number: 56600

Field Name: LADY K

Field Number: 47680

## Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.576928

Longitude: -104.067168

GPS Data: GPS Quality Value: 2.5 Type of GPS Quality Value: Date of Measurement: 10/06/2010

Reason for Abandonment: ☐ Dry ☒ Production Sub-economic ☐ Mechanical Problems☐ OtherCasing to be pulled: ☐ Yes ☒ No Estimated Depth:Fish in Hole: ☐ Yes ☒ No If yes, explain details belowWellbore has Uncemented Casing leaks: ☐ Yes ☐ No If yes, explain details below

Details:

## Current and Previously Abandoned Zones

| Formation | Perf. Top | Perf. Btm | Abandoned Date | Method of Isolation | Plug Depth |
|-----------|-----------|-----------|----------------|---------------------|------------|
| D SAND    | 6796      | 6804      |                |                     |            |

Total: 1 zone(s)

## Casing History

| Casing Type | Size of Hole | Size of Casing | Grade | Wt/Ft     | Csg/Liner Top | Setting Depth | Sacks Cmt | Cmt Btm | Cmt Top | Status |
|-------------|--------------|----------------|-------|-----------|---------------|---------------|-----------|---------|---------|--------|
| SURF        | 12+1/4       | 10+3/4         | J-55  | 32.75     | 0             | 97            | 75        | 97      | 0       | VISU   |
| 1ST         | 7+7/8        | 4+1/2          | J-55  | 10.5&11.6 | 0             | 6948          | 200       | 6948    |         |        |

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 6750 with 2 sacks cmt on top. CIBP #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 50 sks cmt from 150 ft. to 0 ft. Plug Type: ANNULUS Plug Tagged: ☐  
Set 10 sks cmt from 150 ft. to 0 ft. Plug Type: CASING Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐

Perforate and squeeze at 6000 ft. with 50 sacks. Leave at least 100 ft. in casing 5950 CICR Depth

Perforate and squeeze at 3500 ft. with 40 sacks. Leave at least 100 ft. in casing 3450 CICR Depth

Perforate and squeeze at 1500 ft. with 40 sacks. Leave at least 100 ft. in casing 1450 CICR Depth

(Cast Iron Cement Retainer Depth)

Set \_\_\_\_\_ sacks half in. half out surface casing from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Tagged: ☐

Set \_\_\_\_\_ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing

Surface Plug Setting Date: \_\_\_\_\_ Cut and Cap Date: \_\_\_\_\_ Number of Days from Setting Surface Plug to Capping or Sealing the Well: \_\_\_\_\_

\*Wireline Contractor: \_\_\_\_\_

\*Cementing Contractor: \_\_\_\_\_

Type of Cement and Additives Used: \_\_\_\_\_

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

There is no CBL for this well. Our plan is to set the CIBP @ 6760' and spot 2 sacks of cement on top of CIBP, then run a CBL to determine the top of the cement. The CBL will be emailed to the area engineer for approval or changes in the plugging orders before we proceed with the plugging operations.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_

Print Name: Jeff Schneider

Title: President

Date: \_\_\_\_\_

Email: jeff@schneiderenergy.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_

Date: \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_

Expiration Date: \_\_\_\_\_

COA Type

Description

|  |  |
|--|--|
|  |  |
|--|--|

### Attachment List

Att Doc Num

Name

|           |                  |
|-----------|------------------|
| 402636136 | WELLBORE DIAGRAM |
| 402636138 | WELLBORE DIAGRAM |

Total Attach: 2 Files

### General Comments

User Group

Comment

Comment Date

|  |  |                        |
|--|--|------------------------|
|  |  | Stamp Upon<br>Approval |
|--|--|------------------------|

Total: 0 comment(s)