

Location

Lease Road:			
Type	Access		
comment:	Unable to access wellsite due to lock on gate.		
Corrective Action:	Provide key, combinations, or alternate method of access to comply with rule 204.	Date:	03/30/2021

Overall Good:

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	_____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 203576 Type: WELL API Number: 001-09136 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 3/30/21 at approximately 1030 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Linnebur 2 Company Name- Western Operating API- 05-001-09136 In Adams County Colorado. While there, I observed SI well. During this inspection the following possible compliance issues were observed: Unable to access wellsite due to lock on gate. Provide key, combinations, or alternate method of access to comply with rule 204. 3/30/21 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	medinaj	03/30/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402644180	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5390449
699502446	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5390437