

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/27/2021

Submitted Date:

04/27/2021

Document Number:

699103460**FIELD INSPECTION FORM**
 Loc ID 329492 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430651	TANK BATTERY	AC	10/30/2012		-	LOLOFF TANK BATTERY 35-6	SI

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	NFPA placard not legible. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	06/04/2021
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	Adequate	Date:	
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	IGNITOR/COMBUSTOR		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbwire		
Corrective Action:		Date:	

**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		

Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV CONCRETE		,	
Comment:	Shares containment with crude oil tanks.					
Corrective Action:						Date:

**Paint**

Condition		
Other (Content)		
Other (Capacity)	48 BBL	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		40.357500,-104.512400
Comment:					
Corrective Action:					

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate	
Comment:	Secondary containment is inadequate to contain 150% of the volume of the largest tank.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.				Date: 06/04/2021

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 430651 Type: TANK API Number: - Status: AC Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 4/27/21 at approximately 1148hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Loloff Tank Battery 35-6 of Noble Energy, at Facility ID # 430651 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>NFPA placard not legible. Install sign to comply with Rule 605.g. With a corrective action date of 6/4/21.</p> <p>"Weathered Berm" Secondary containment is inadequate to contain 150% of the volume of the largest tank. Repair or install berms or other secondary containment devices per Rule 603.o. With a corrective action date of 6/4/21.</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	04/27/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402672960	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5414670">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5414670</a>
699103461	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5414660">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5414660</a>