

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/06/2021

Submitted Date:

05/06/2021

Document Number:

699103584

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
410006 _____ Burns, Adam _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10071
Name of Operator: HIGHPOINT OPERATING CORPORATION
Address: 555 17TH ST STE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 12 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Paben, Brett		bpaben@hpres.com	All Inspections
Frishmuth, Rusty		rfrishmuth@hpres.com	All Inspections
Reese, Jason		jreese@hpres.com	All Inspections
Neighbors, Cory		cneighbors@hpres.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
132	WELL	PR	01/01/2019	GW	123-25423	PETERSON 30-31	PR

General Comment:

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Adequate		Date: _____
Corrective Action:			
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment next to the well, needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606		Date: <u>05/17/2021</u>
Type	OTHER		
Comment:	Stained soil next to the well needs to be removed. See attached photo.		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."		Date: <u>05/17/2021</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:			Date:
Equipment:			
			corrective date
Type: Other	#		
Comment:	Master valves appear to be leaking, fix or replace. See attached photo.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: <u>05/17/2021</u>
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface.		
Corrective Action:			Date:
Venting:			
Yes/No	NO		

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 132 Type: WELL API Number: 123-25423 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 09/02/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 5/6/21 at approximately 1155hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Peterson 30-31 of Highpoint Resources, at Location ID # 410006 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Unused equipment needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/17/21 Stain soil next to the well needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 5/17/21 Master valves appear to be leaking, fix or replace. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. With a corrective action date of 5/17/21 See attached photos. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	burnsa	05/06/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402681977	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5422659
699103585	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5422650