

TEP
KP 34-18
Location # 335529



location



location

TEP
KP 34-18
Location # 335529



Signage in front of separators is illegible



Lack of battery signage

TEP
KP 34-18
Location # 335529



Staining



Staining

TEP
KP 34-18
Location # 335529



Unmarked dead men



Inlet side culvet

TEP
KP 34-18
Location # 335529



Outlet side culvert



Culvert

