

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/22/2021

Submitted Date:

07/23/2021

Document Number:

690201861**FIELD INSPECTION FORM**Loc ID 308367 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10351Name of Operator: WAPITI OPERATING LLCAddress: 1310 W SAM HOUSTON PKWY NCity: HOUSTON State: TX Zip: 77043**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
MADISON RANDY		rmadison@wapitienergy.com	
MATTORANO MIKE		mmattorano@wapitienergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269528	WELL	PR	08/13/2010	GW	071-07915	VPC C 121	RI

General Comment:

This is a stormwater management inspection.
See attached photos and additional details within this report.

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There was a significant percipitation event in this area which has caused erosion along the main road traveling to the location. There are culverts that will need to be repaired. Areas of erosion will need to be repaired and stabilized.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C Date: 09/01/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
It was obsrved that noxious weed control was performed along the road. There were somes weeds wilted but ongoing weed control should be performed.	CostaR	07/23/2021
There was a significant percipitation event in this area. An extended corrective action date was provided due to required stormwater repairs in other areas.	CostaR	07/23/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402758953	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5488234
690201862	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5488230