

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/03/2021

Submitted Date:

09/07/2021

Document Number:

690202038

FIELD INSPECTION FORMLoc ID 308029 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD State: CO Zip: 8111-

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fitzgerald, Edie		efitzgerald@ogrisop.com	
ATWATER BONNIE		batwater@ogrisop.com	
Mack, Ronald		rmack@ogrisop.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260246	WELL	PR	08/10/2011	GW	071-07412	APACHE CANYON 18-15V	RI

General Comment:

This is a follow up of the previous stormwater management inspections; #690200851, #690201821.
The corrective action of the previous inspections have not been performed.
See attached photos and additional details within this report.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
	WELLHEAD			
Comment:	There are stained soils at the wellhead.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: <u>10/07/2021</u>

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [There is vehicle rutting and erosion along the access road ascending the hill toward the location. Areas of erosion along the road must be repaired and properly stabilized. Previous corrective action was not performed.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 12/23/2020

Pits: ☐ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	268875	1121974	

COGCC Comments

Comment	User	Date
Change of Operator is listed as OGRIS OPERATING LLC.	CostaR	09/07/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402804139	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5525312
690202039	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5525306