

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/11/2021

Submitted Date:

10/14/2021

Document Number:

699104589

FIELD INSPECTION FORM

Loc ID 327605 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 4 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections

General Comment:

This is a follow up to prior inspection document #699104322 & #699104376. Well Sign is still missing.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Well is missing well sign and needs installed. See attached photos		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	09/10/2021

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>

Flaring:

Type			
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 10/11/21 at approximately 1020hrs, I, Inspector Adam Burns, Conducted an on-site inspection to prior inspection documents # 699104322 & #699104376 at Ocoma 31-19 of K.P. Kauffman, at Location ID # 327605 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Well is missing well sign and needs installed. Install sign to comply with Rule 605.d. With a corrective action date of 9/10/21 See attached photos. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	burnsa	10/14/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402841799	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5555021

699104590	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5555018
-----------	-------------------	---