

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/19/2021

Submitted Date:

10/19/2021

Document Number:

693505620

FIELD INSPECTION FORM
 Loc ID 318254 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 31257

Name of Operator: FRITZLER RESOURCES INC

Address: P O BOX 114

City: FORT MORGAN State: CO Zip: 80701

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240980	WELL	PR	09/01/2020	GW	123-08768	B C HOPKINS 31-19 (1-67) 3	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	"Sign not legible Sign not updated to reflect current operator"	
Corrective Action:	Install sign to comply with Rule 605.g.	Date: 11/19/2021

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type			
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:		
Type		

Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 240980 Type: WELL API Number: 123-08768 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: Fluid Type:

End Surf Csg Pressure:

Comment: No reports on file

11/19/2021

Corrective Action: Comply with COGCC annual bradenhead testing rules 419.

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday October 19, 2021 at approximately 9:36AM, I, Inspector Randy Silver, conducted an on-site inspection.</p> <p>Location: BC Hopkins 31-19 (1-17) #3</p> <p>Operator: Fritzler Resources</p> <p>API#:123-08768</p> <p>County: Weld</p> <p>While there, I observed producing well site</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Sign: Rule 605 g Corrective action date of 11-19-21</p> <p>Braden head: Rule 419 Corrective action date of 11-19-21.</p> <p>Weather conditions: Cloudy</p> <p>This is a follow up inspection per doc#699503006. At time of inspection corrective actions appear to have not been addressed.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	10/19/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402846295	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5558590
693505621	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5558584