

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/25/2021

Submitted Date:

10/25/2021

Document Number:

693505666

FIELD INSPECTION FORM

Loc ID 318212 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 7 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
,	303-825-4822	cogcc@kpk.com	All Inspections
Canfield, Chris		chris.canfield@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240886	WELL	PR	05/26/1976	OW	123-08674	UPRR 43 PAN AM I 5	SI

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	OTHER		
Comment:	Storm water; BMP's improperly installed or not installed at all.		
Corrective Action:	Comply with rule 1002.	Date:	10/26/2021

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	Hog fence		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 240886 Type: WELL API Number: 123-08674 Status: PR Insp. Status: SI**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: _____Comment: Well is shut in due to flow lines being capped due to what appears to have been a leak.

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 10/22/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday October 25, 2021 at approximately 12:24PM, I, Inspector Randy Silver, conducted an on-site inspection. Location: UPRR 43 Pan AM I #5 Operator: KP Kauffman API#: 123-08674 County: Weld While there, I observed a well site and active spill remediation activity. During this inspection the following possible compliance issues were observed: Storm water: Rule 1002 Corrective action date of 10-26-22 See photos 3,4,5,7 Weather conditions: Clear At time of inspection I drove up on an active spill remediation project. Crew was actively digging and loading semi with what appeared to be contaminated soil. I did ask truck driver for shipping papers he did provide them. It appears material is going to Front Range land fill. I spoke with Forman on site asked him about his Storm water for construction site. He stated they installed a liner under contaminated soil and laying down straw waddles around pile. He was not aware of any other BMP's for work site. KPK will need to contact the Environmental department and Pipe line integrity group whit the COGCC. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	10/25/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402852079	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5563272
693505667	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5563270
693505668	loc pic 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5563271