

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/05/2022

Submitted Date:

01/05/2022

Document Number:

693506177

FIELD INSPECTION FORM

Loc ID 318749 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
4 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
,	303-825-4822	cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242099	WELL	PR	08/01/2017	GW	123-09890	UPRR 43 PAN AM I 30	PR

General Comment:

Location			
Lease Road:			
Type			
comment:	No road open field		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	ADequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Mechanical issue : Well head actively leaking around tubing at time of inspection		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: <u>02/05/2022</u>
Type	UNUSED EQUIPMENT		
Comment:	Unused PU base		
Corrective Action:	Comply with rule 606		Date: <u>02/05/2022</u>
Type	OTHER		
Comment:	Unmarked electric risers are unused equipment		
Corrective Action:	Comply with rule 606		Date: <u>02/05/2022</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type			
Comment:			
Corrective Action:			Date:
Equipment:			
Type: Bradenhead	# 0		corrective date
Comment:	Bradenhead inaccessible or not visible		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)		Date: <u>02/05/2022</u>

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 242099 Type: WELL API Number: 123-09890 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Flow line valve at time of inspection was in the closed position.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 10/28/2021 Annual Brhd Completed?

Last Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type:

End Surf Csg Pressure: --

Comment: No visual piping for braden head.

Corrective Action: Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday January 5, 2022 at approximately 12:33PM, I, Inspector Randy Silver, conducted an on-site inspection. Location: UPRR 43 PAN AM I #30 Operator: KP Kauffman API#: 123-09890 County: Weld While there, I observed a Shut in well head During this inspection the following possible compliance issues were observed: Braden head: Rule 41 a (1) Corrective action date of 2-5-22 See photo 4 Unused equipment: Rule 606 Corrective action date of 2-5-22 See photo 3 Unmarked riser: Rule 606 Corrective action date of 2-5-22 see photo 2 Mechanical issue: Rule 608 e Corrective action date of 2-5-22 See video. Weather conditions: Cloud I spoke with Mani Silva at approx.. 12:37 informed him that the well head was leaking. He stated he would send someone as soon as possible. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	01/05/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402917916	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5625179
693506178	video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5625177
693506179	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5625178