



Left Field 31-29



Drilling mud in pit has been cleaned up and re-seeded to comply with Rule 902.b.





Oily rag removed to comply with Rule 606





Installed or repaired required BMPs per Rule 1002.f.(2)C





Installed or repaired required BMPs per Rule 1002.f.(2)C





Installed or repaired required BMPs per Rule 1002.f.(2)C





Installed or repaired required BMPs per Rule 1002.f.(2)C





Installed or repaired required BMPs per Rule 1002.f.(2)C





Installed or repaired required BMPs per Rule 1002.f.(2)C





Fixed vehicle tracks raked and repaired; all oil and gas vehicle will stay inside within access road to comply with Rule 1002.e.









Erosion issues with culvert have been repaired