

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE

Location ID: 335010



Photo #6116 from entrance to location.



Photo #6117 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE

Location ID: 335010



Photo #6118 Location lacks stabilization.



Photo #5645 from inspection #699803991 conducted on 1/12/22.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE

Location ID: 335010



Photo #6119 Location lacks stabilization.



Photo #5646 from inspection #699803991 conducted on 1/12/22.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE

Location ID: 335010



Photo #6120 Location lacks stabilization.



Photo #6121 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE

Location ID: 335010



Photo #6122 Insufficient tracking control at entrance to location.