



00051830

COLORADO OIL & GAS CONSERVATION COMMISSION

FIELD INSPECTION REPORT

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION	1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100				
API No. 05- 013 - 6137-1	LEASE NAME: VICKLAND G # 1				
LOCATION: NW NE 2 IN 69W	OPERATOR: VESSELS				
DATE: 7/24/96	INSPECTOR: SHELTON				
Insp. Type: PR	Insp. Status: PR	PA: Y N	Pass/Fail: P <input checked="" type="radio"/> F	Viol. <input checked="" type="radio"/> Y N	NOV: Y N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)	OK	
Pits (Reserve/Production) (Rule 902, 903, 904)	BURIED METAL TANK Ⓢ	
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)	2-100, HT, GMR JUST EAST OF WELL	
Fire Walls/Berms/Dikes (Rule 604)	INADEQUATE	
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)	OLD OIL STAINED SOIL IN TANK BERM	
Bradenhead (Rule 207)	NO ACCESS	
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)		
Miscellaneous	PLUNGER LIFT	

CORRECTIVE ACTION REQUIRED: REBUILD FRONT OF TANK BERM, REMOVE OLD OIL STAINED SOIL
Date Corrective Action Required By: 8/24/96 Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.