

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/30/2022

Submitted Date:

03/31/2022

Document Number:

700901093**FIELD INSPECTION FORM**Loc ID 320104 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10695Name of Operator: BEHRENS RESOURCES INCAddress: PO BOX 188City: DEER TRAIL State: CO Zip: 80135**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		GDean@adcogov.org	
Behrens, Vic	303-810-6382	behrens@netecin.net	Inspections
Leonard, Mike		mike.leonard@state.co.us	
		GDean@adcogov.org	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202647	WELL	SI	06/01/2018	OW	001-08052	C LISCO 14-31	SI

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Access road unmaintained		
Corrective Action:	Maintain access roads per Rule 204. Corrective Action Date 4/29/2022.	Date:	04/29/2022

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Emergency contact Sign not updated to reflect current operator.	Date:	04/29/2022
Corrective Action:	Emergency contact Sign not updated to reflect current operator. Install sign to comply with Rule 605.g. 30 days if missing 24 hour operator contact number and/or local emergency contact. Corrective Action date 4/29/2022. See photo #1.		

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Mechanical Conditions. Packing leaking on well head,		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. If leak is found immediately call to operator, 24 hours to fix the leak or isolate leak. Corrective Action 24hrs. See attached videos.	Date:	04/02/2022

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 202647 Type: WELL API Number: 001-08052 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Appears to be plumbed to surface

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday March 30, 2022 at approximately 13:00pm. I, Inspector Chane Finkenbinder, conducted an on-site inspection at C Lisco 14-31, Behrens Resources, at API # 001-08052 in Adams County Colorado.</p> <p>While there, I observed a shut in well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Mechanical Conditions. Packing leaking on well head. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. If leak is found immediately call to operator, 24 hours to fix the leak or isolate leak. Corrective Action 24hrs. See attached videos.</p> <p>Access road unmaintained. Maintain access roads per Rule 204. Corrective Action Date 4/29/2022.</p> <p>Emergency contact Sign not updated to reflect current operator. Install sign to comply with Rule 605.g. 30 days if missing 24 hour operator contact number and/or local emergency contact. Corrective Action date 4/29/2022. See photo #1.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	finkenbc	03/31/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403001291	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5710995
700901094	Inspection photos and videos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5710993