

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/21/2022

Submitted Date:

04/22/2022

Document Number:

690202811

**FIELD INSPECTION FORM**Loc ID 308378 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
BACA DAVID		dbaca@ogrisop.com	
ATWATER BONNIE		batwater@ogrisop.com	
GEE, GREG		ggee@ogrisop.com	
WARD, GIENA		gward@ogrisop.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270571	WELL	PR	03/01/2021	GW	071-07944	APACHE CANYON 1-14	RI

**General Comment:**

This is a follow up of the previous stormwater management inspection #690201879.  
The corrective action of the previous inspection has not been performed.  
See attached photos and additional details within this report.

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Fail			

Comment: The road in the canyon bottom is not maintained or stabilized. The road was graded and soil material is pushed up along the side which will prevent stormwater drainage. The culverts along the road are not maintained. The road must be repaired and stabilized. BMP's must be implemented in accordance with good engineering practice and must be maintained. Previous corrective action has not been completed however, work was being performed at the nearby road.

Corrective Action: **Install or repair required BMPs per Rule 1002.f.(2)C**

Date: 05/14/2021

Pits: ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403025774	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5733543">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5733543</a>
690202814	OTHER	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5733459">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5733459</a>