



**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:	Sign not posted at well, see attached photo.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	07/29/2022

**Emergency Contact Number:**

Comment:

Corrective Action: Install sign to comply with Rule 605.d.

Date: 07/29/2022

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

		#		corrective date
Type: Flow Line		# 1		
Comment:				
Corrective Action:				Date:
Type: Bradenhead		# 1		
Comment:	Bradenhead valve is exposed at surface.			
Corrective Action:				Date:
Type: Plunger Lift		# 1		
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 284354 Type: WELL API Number: 123-23789 Status: PR Insp. Status: SI

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 02/15/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass	Seeding	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>                      On Friday 4/22/2022 at approximately 11:15 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the KPK Anderson 13-32 location #332701 in Weld County, Colorado.                      While there, I observed that the wellhead sign and emergency contact number were not posted. During this inspection the following possible compliance issues were observed: Rule 605.d. with a corrective action date of 7/29/2022.                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of the inspection report.</p>	petersont	04/22/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403025789	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5733556">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5733556</a>
697005719	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5733479">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5733479</a>