

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/31/2022

Submitted Date:

06/01/2022

Document Number:

690202968

FIELD INSPECTION FORMLoc ID 481116 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10767

Name of Operator: TWIN BRIDGES RESOURCES LLC

Address: 475 17TH ST., STE 900

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kosola, Jason		jason.kosola@state.co.us	
WALLACE TOM		tcw@twinbridgesllc.com	
ROGOWSKI KELLY		krogowski@twinbridgesllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481333	WELL	DG	04/02/2022		071-09919	Red Rocks 35-15	RI

General Comment:

This is a Location Construction Inspection. The well was drilled as of 4/2/2022.
See attached photos and additional details within this report.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign posted at wellhead and entrance of location.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	There is equipment being stored near the location which will need to be removed. Equipment storage will create additional disturbance. Associated disturbance will need to be reclaimed. Vehicles and equipment shall not travel outside of original access road and location boundary.		
Corrective Action:	Comply with Rule 606	Date:	06/30/2022
Type	OTHER		
Comment:	The wellhead cellar needs to be covered to prevent livestock/wildlife entry.		
Corrective Action:	Comply with 602.c.	Date:	06/08/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Location Construction

Location ID: 481333 CDP: _____

Comment: There was no form 42 Notice submitted for Construction. Operators will provide the Commission written notice 2 business days in advance of commencing construction or a major change at any Oil and Gas Location or Oil and Gas Facility. Operator did not comply with Rule 405.b.

Corrective Action: _____ **Date:** _____

Form 2A COAs:**Comment:** _____

Corrective Action: _____ **Date:** _____

Wildlife BMPs:**Comment:** _____

Corrective Action: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Comments: Erosion BMPs: The straw wattles are not properly installed and do not completely protect down gradient runoff from disturbed areas.

Other BMPs: _____

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C **Date:** 06/08/2022

2

Comment: There are multiple soil piles on location. Soil piles need to properly marked and stored. Soil piles need to be protected and stabilized per Rule 1002.c.

Corrective Action: _____ **Date:** _____

On Site Inspection (305):Surface Owner Contact Information:

Name: _____ **Address:** _____
Phone Number: _____ **Cell Phone:** _____

Operator Rep. Contact Information:

Landman Name: _____ **Phone Number:** _____
Date Onsite Request Received: _____ **Date of Rule 306 Consultation:** _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ **Phone Number:** _____ **Agreed to Attend:** _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Drill Cuttings	Piles	Inadequate		
Comment:	There are multiple piles on location which at least one pile may be drill cuttings. There has been no form 27 submitted for burial in a Cuttings Trench and there are piles sitting on the soil surface with inadequate stormwater protection.			
Corrective Action:	Comply with 905.g. COGCC EPS staff (Jason Kosola) for directives.			Date: 06/02/2022

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): Comment: Pilot: Wildlife Protection Devices (fired vessels): **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403064406	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5767696
690202969	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5767694