

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/10/2022

Submitted Date:

06/10/2022

Document Number:

699105542

**FIELD INSPECTION FORM**Loc ID 414881 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
414994	WELL	PR	02/01/2022	GW	123-30941	STINAR C 13-32	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Adequate		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil next to the well needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606.		Date: 06/21/2022

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 414994 Type: WELL API Number: 123-30941 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 03/31/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 6 /8/22 at approximately 0hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Stinar C 31-32 of Chevron, at API # 05-123-30941 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained soil next to the well need to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 6/21/22</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	06/10/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403075944	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5776887">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5776887</a>
699105543	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5776884">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5776884</a>