

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403083655

Date Received:

06/20/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10663

Name of Operator: ENDURING RESOURCES LLC

Address: 6300 S SYRACUSE WAY, SUITE 525

City: CENTENNIAL State: CO Zip: 80111

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Walter, Kyle

kwalter@enduringresources.com

Huntington, Heather

hhuntington@enduringresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693904496

Inspection Date: 05/13/2022

FIR Submit Date: 05/16/2022

FIR Status: _____

Inspected Operator Information:

Company Name: ENDURING RESOURCES LLC

Company Number: 10663

Address: 6300 S SYRACUSE WAY, SUITE 525

City: CENTENNIAL State: CO Zip: 80111

LOCATION - Location ID: 326325

Location Name: W. ANIMAS-WHEELER- Number: 8SWSE County: LA PLATA
N34N9W

Qtrqr: SWSE Sec: 8 Twp: 34N Range: 9W Meridian: N

Latitude: 37.216843 Longitude: -107.872406

FACILITY - API Number: 05-067- -00 Facility ID: 216235

Facility Name: W. ANIMAS-WHEELER Number: 8-1

Qtrqr: SWSE Sec: 8 Twp: 34N Range: 9W Meridian: N

Latitude: 37.216843 Longitude: -107.872406

CORRECTIVE ACTIONS:

1 ☒ CA# 161978

Corrective Action: -Operator needs to assess, treat, monitor and manage for jointed goatgrass by 5/30/2022. Spot seeding/mulching may be needed if desirable perennial vegetation is not becoming established here.

Date: 05/30/2022

Response: CA COMPLETED

Date of Completion: 05/30/2022

Operator Comment: Jointed goat grass sprayed to kill the top section, the bottom section was sprayed last year. Plan to disk in and replant later this year.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2  CA# 161979

Corrective Action: -Assess stormwater erosion and determine whether perimeter BMPs remain needed.
Silt fence needs to be repaired or removed by 6/15/2022.

Date: 06/15/2022

Response: CA COMPLETED

Date of Completion: 06/15/2022

Operator
Comment:

SILT FENCE HAS BEEN REPAIRED

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Heather Huntington

Signed: _____

Title: Permitting Tech

Date: 6/20/2022 8:53:41 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

| | |
|-----------|--------------------------|
| 403083655 | FIR RESOLUTION SUBMITTED |
| 403083658 | ca photos |

Total Attach: 2 Files