

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2022

Submitted Date:

07/12/2022

Document Number:

699105686**FIELD INSPECTION FORM**Loc ID 459542 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 2001 16TH STREET SUITE 900City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459552	WELL	PR	01/12/2022	OW	123-48941	Guttersen D09-745	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Adequate		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil in multiple spots needs to be removed. See attached photos.		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."		Date: 07/22/2022
Type	TRASH		
Comment:	White broken tube needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606		Date: 07/22/2022
Type	UNUSED EQUIPMENT		
Comment:	Unused tote needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606		Date: 07/22/2022

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 459552 Type: WELL API Number: 123-48941 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 01/19/2022Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 7/11/22 at approximately 0938hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Gutteresen D09-745 of Chevron, at API # 05-123-48941 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused tote needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 7/22/22</p> <p>White broken tube needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 7/22/22</p> <p>Stained soil in multiple spots needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 7/22/22</p> <p>See attached photos.</p> <p>Submit pictures on FIRR.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	07/12/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
699105687	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5800220