

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Adequate		Date:
Corrective Action:			

Good Housekeeping:			
Type	TRASH		
Comment:	White broken tube needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606	Date:	07/22/2022
Type	UNUSED EQUIPMENT		
Comment:	Unused tote needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606	Date:	07/22/2022
Type	OTHER		
Comment:	Stained soil in multiple spots needs to be removed. See attached photos.		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date:	07/22/2022

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 459552 Type: WELL API Number: 123-48941 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/19/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 7/11/22 at approximately 0938hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Guttersen D09-745 of Chevron, at API # 05-123-48941 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Unused tote needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 7/22/22 White broken tube needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 7/22/22 Stained soil in multiple spots needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 7/22/22 See attached photos. Submit pictures on FIRR. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	burnsa	07/12/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403101919	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5800233
699105687	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5800220