

Sandlin Oil Corp, Tippet-Carlson 1
005-06646

Inspection #688312793

7/20/2022

Routine Field Inspection



Colorado Oil and Gas Conservation Commission
39.73744, -104.2624, 5193.6ft, 224°
07/20/2022 01:34:53 PM



Stained soil at wellhead.

Colorado Oil and Gas Conservation Commission
39.73742, -104.26242, 5187.0ft, 194°
07/20/2022 01:35:07 PM



Colorado Oil and Gas Conservation Commission
39.73748, -104.26243, 5180.4ft, 158°
07/20/2022 01:35:31 PM



Colorado Oil and Gas Conservation Commission

39.73749, -104.26243, 5183.7ft, 351°

07/20/2022 01:35:19 PM



Colorado Oil and Gas Conservation Commission
39.73871, -104.26263, 5173.9ft, 206°
07/20/2022 01:37:18 PM



Control
weeds.

Colorado Oil and Gas Conservation Commission

39.73872, -104.26269, 5173.9ft, 184°

07/20/2022 01:37:44 PM



Colorado Oil and Gas Conservation Commission
39.73861, -104.26262, 5177.2ft, 244°
07/20/2022 01:36:42 PM



Colorado Oil and Gas Conservation Commission
39.73858, -104.2624, 5177.2ft, 40°
07/20/2022 01:39:10 PM



Stained soil at
treater inside
berms.

Colorado Oil and Gas Conservation Commission
39.7386, -104.26232, 5177.2ft, 37°
07/20/2022 01:39:32 PM



Colorado Oil and Gas Conservation Commission
39.73869, -104.26235, 5183.7ft, 96°
07/20/2022 01:41:09 PM



Colorado Oil and Gas Conservation Commission
39.73871, -104.26261, 5177.2ft, 119°
07/20/2022 01:37:26 PM



Colorado Oil and Gas Conservation Commission
39.7385, -104.26216, 5173.9ft, 135°
07/20/2022 01:40:30 PM



Gas sales line.

Colorado Oil and Gas Conservation Commission
39.73866, -104.26225, 5164.0ft, 358°
07/20/2022 01:39:58 PM