

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/17/2022

Submitted Date:

08/26/2022

Document Number:

696203998**FIELD INSPECTION FORM**Loc ID 479185 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, "		COGCC.inspections@caerus oilandgas.com	All Inspections

General Comment:

On 8/17/2022, Reclamation Specialist Trujillo conducted a pre-drill, construction and stormwater inspection at Caerus Piceance LLC's ELU O13-496 Pad location in Rio Blanco County, Colorado.

This inspection is also a followup to #696203892 to document compliance with the following:

-Location signage not posted

The following compliance issues were observed during this inspection:

-Oil and Gas Location Signage not posted

-Location Assessment (Form) 2A not

Refer to the "Construction" and "Location" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type			
Comment:	Inspection #696203892 observed that Location signage for the ELU /O13-496 Pad was not posted at the Location. Inspection required Operator to comply with 605.a. It was observed in this inspection that signage per Rule 605.a remains missing. Reclamation Specialist discussed issue with Operator, and was notified that signage has been ordered. Corrective action remains applicable.		
Corrective Action:	Comply with Rule 605.a.	Date:	07/20/2022

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location Construction

Location ID: 479185 CDP: _____

Comment: Inspection #696203892 observed that a copy of the approved Form 2A, and any Form 4 modifying the approve Form 2A has not been posted on the Location. Inspection required Operator to comply with 406.c. It was observed in this inspection that permit information has not been posted in a protected and conspicuous place on location

Corrective Action: Comply with Rule 406.c.

Date: 07/20/2022

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective Action: _____

Date: _____

On Site Inspection (305):Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403148401	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5840914
696203999	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5840908