

**Motu East Pad – Facility ID 439455– Status: PR**

**Doc #: 697504024**

**Follow up to field inspection report doc  
#697500782**

DUE DATE for corrective action: [11/21/2022](#)

**Corrective Action 5**-Operator shall redo the revegetation in accordance to Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use an approved seed mixture provided by the local NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management. Operator shall provide the seed mixture in the required FIRR response. Revegetation activities shall be complete no later than 11/21/22 or as soon as environmental conditions will permit.

The corrective action was completed on 10/29/2022 by CB Services. Re seeding was done in accordance with the approved seed mixture by the landowner.



**Photo 6.** Photo taken from the northern interim reclamation area, facing East. Photo illustrates interim reclamation has been performed; however, an introduced seed mix was used which is not reflective of reference area vegetation per Rule 1003.

Pics of the corrective action being addressed on 10/29/2022:



