

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/28/2022

Submitted Date:

12/15/2022

Document Number:

699700351

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: Heil, John On-Site Inspection
 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Operator Information:

OGCC Operator Number: 10775

Name of Operator: KT RESOURCES LLC

Address: 3381 WESTBROOK LANE

City: HIGHLANDS State: CO Zip: 80129

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Longworth, Mike		michael.longworth@state.co.us	
Gale, Anthony	3038868733	tony@kt-res.com	Co-owner

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
483021	SPILL OR RELEASE	AC	10/05/2022		-	SPILL/RELEASE POINT	EI

General Comment:

On November 28, 2022, COGCC Environmental Staff (John Heil) conducted an environmental field inspection of KT RESOURCES LLC (Operator #10775) Spill/Release #483021 and the associated Remediation Project #26377.

KT Resources reported the Spill/Release to COGCC on September 29, 2022.

Inspected Facilities

Facility ID: 483021 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: See Spill/Release ID 483021 and Remediation Project #26377 for more information. The excavation containing the 3-inch HDPE produced water line observed during 11/8/2022 Inspection (Doc #699700347) was backfilled and the stockpiles of apparent E&P impacted soil around the excavation were no longer present. Apparent E&P waste with potential salt staining was observed in the area of the backfilled excavation. See attached Photo Log for details.

Corrective Action: Operator shall with COAs on Form 19 Doc #403239417 and Form 27 Doc #403229607. Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403262646	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5946320
699700352	20221128 Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5946315