

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/16/2022

Submitted Date:

12/16/2022

Document Number:

694100039

FIELD INSPECTION FORM

Loc ID 331031 Inspector Name: Robinson, Taylor On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 16700
Name of Operator: CHEVRON USA INC
Address: 760 HORIZON DRIVE STE 401
City: GRAND JUNCTION State: CO Zip: 81506

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		nbl_djbu_inspections@nblenergy.com	ALL INSPECTIONS ONLY
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

General Comment:

This is an environmental inspection for Location ID: 331031 Noble Beeler 22-11. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location Construction

Location ID: 331031 CDP: _____

Comment:

Corrective Action:

Date: _____

Form 2A COAs:

Comment:

Corrective Action:

Date: _____

Wildlife BMPs:

Comment:

Corrective Action:

Date: _____

Comment:

Corrective Action:

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)	
Comment	Soil stockpile present with no erosion control.			
Corrective Action	For localized stained soils or oily waste - ""Properly dispose of oily waste in accordance with 905.e. Install or repair required BMPs per Rule 1002.f.(2)C			Date: 12/23/2022

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403264816	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5951004
694100041	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5950998