

# Inspection Photos

2/27/2023

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location #334745

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location #334745



**Photo 1:** Photos 1- 7 shows that BMPs to stabilize the Location, and to minimize degradation, tracking and sediment transport from the working pad areas are missing or insufficient. Photos 1-2 also show off-site sediment transport onto the adjacent county road.





## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334745



February 27, 2023

**Photo 2:** See comments under photo 1.



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location #334745



February 27, 2023

**Photo 3:** See comments under photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location #334745



**Photo 4:** See comments under photo 1.



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location #334745



February 27, 2023

**Photo 5:** See comments under photo 1.



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location #334745



**Photo 6:** See comments under photo 1.





## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334745



**Photo 7:** See comments under photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334745



**Photo 8:** Photos taken from the northeast end of the Location. Photo shows erosion degradation on the interim areas of the location, due to runoff from the working pad. Surface roughening alone inadequate.



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location #334745



February 27, 2023



February 27, 2023

**Photo 9:** Photos taken from adjacent areas of the tank battery. Photo shows spill outside of containment and stained soils.



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location #334745



**Photo 10:** Wildlife protection BMPs not in proper functioning condition.

