

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/29/2023

Submitted Date:

04/03/2023

Document Number:

702801416

**FIELD INSPECTION FORM**Loc ID 324048 Inspector Name: O'Malley, Anna On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211573	WELL	PR	08/02/2001	GW	045-07333	FORCE RMV #113-33	RI
324048	LOCATION	AC			-	FORCE-66S94W 33NWSE	RI

**General Comment:**

On 3/29/2023, Reclamation Specialist O'Malley conducted an interim reclamation and stormwater inspection at TEP ROCKY MOUNTAIN LLC's FORCE-66S94W/33NWSE Location #324048 in Garfield County, Colorado.

The following compliance issues were observed during this inspection:

- Noxious weeds
- Staining
- Stormwater: erosion, sediment transport, site degradation

Refer to the Location, "Reclamation" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Bull thistle (List B Noxious) observed in the interim area to the south of the location.		
Corrective Action:	Conduct weed management to prevent further establishment and spread of noxious weeds; ongoing weed management required until location passes final reclamation.		Date: 05/01/2023
Type	OTHER		
Comment:	Stained gravel observed to the north of the wellhead.		
Corrective Action:	Conduct maintenance on equipment if necessary, cleanup stained material and review self inspection processes.		Date: 04/08/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>211573</u>	Type:	<u>WELL</u>	API Number:	<u>045-07333</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>324048</u>	Type:	<u>LOCATION</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>RI</u>

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? <u>Pass</u>	Production areas stabilized ? <u>Pass</u>
1003c. Compacted areas have been cross ripped? _____	
1003d. Drilling pit closed? _____	Subsidence over on drill pit? _____
Cuttings management: _____	
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? <u>In</u>	
Production areas have been stabilized? <u>Pass</u>	Segregated soils have been replaced? _____

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced _____	Recontoured _____	Perennial forage re-established _____
-------------------------	-------------------	---------------------------------------

Non-Cropland

Top soil replaced _____	Recontoured <u>Pass</u>	80% Revegetation <u>In</u>
-------------------------	-------------------------	----------------------------

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? F

Comment 
[Refer to the "Location" section of this report for weed control corrective action.](#)  
  
 Areas of the location not needed for production have been reduced and reclaimed. The location is in an ephemeral drainage. A runon diversion berm appears to have created a small depressional wetland. Interim vegetation is colonized by hydrophytic species. Upland interim areas are vegetated with perennial grasses and shrubs. Dormant season prevented a full vegetation assessment. A follow up inspection will be conducted during a future growing season to determine compliance with 1003 requirements.

Corrective Action  Date \_\_\_\_\_

Overall Interim Reclamation In Process

---

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged _____	Pit mouse/rat holes, cellars backfilled _____
Debris removed _____	No disturbance /Location never built _____
Access Roads _____	Regraded _____ Contoured _____ Culverts removed _____
Gravel removed _____	
Location and associated production facilities reclaimed _____	Locations, facilities, roads, recontoured _____
Compaction alleviation _____	Dust and erosion control _____
Non cropland: Revegetated 80% _____	Cropland: perennial forage _____
Weeds present _____	Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment:		
Corrective Action:		Date
Overall Final Reclamation	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Culverts						
Gravel						
Compaction		Gravel				
Berms		Compaction				
Rip Rap						

Comment:	Insufficient stormwater and sediment control BMPs in place. The cut slope at the east of the location is actively eroding. Rill erosion is widespread on the slope. Sediment lost from the slope is accumulating at the base, smothering vegetation and contributing to stormwater sediment loads. The southeastern portion of the cut does not have rills, rather it appears that whole portions of the slope are sloughing off. Pedestals are present around slope vegetation. The top of the cut is undermining resulting in erosion, exposed roots and degradation to undisturbed areas above the cut.					
Corrective Action:	Install or repair required BMPs per Rule 1002.f. Continue to monitor and manage stormwater on the Location. Ongoing stormwater management is required until the site receives a passing final inspection.					Date: 04/06/2023

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403363885	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6070721">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6070721</a>
702801417	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6070716">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6070716</a>