

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/19/2023

Submitted Date:

04/19/2023

Document Number:

702501160

FIELD INSPECTION FORM

Loc ID: 316142 Inspector Name: Burchett, Kirby On-Site Inspection: 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments

7 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 10775

Name of Operator: KT RESOURCES LLC

Address: 3381 WESTBROOK LANE

City: HIGHLANDS State: CO Zip: 80129

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	
Adams, Karen	(303) 886-8733	adams@kt-res.com	
Gale, Tony	(303) 886-8733	tony@kt-res.com	
Baumgras, Dan		Dan@KT-Res.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232230	WELL	PR	05/01/2022	GW	103-09901	WRD WYATT 36-23	PR

General Comment:

[COGCC Inspection Report Summary](#)

On Wednesday, 4/19/2023, Inspector Kirby Burchett, conducted a routine field inspection at KT Resources on the WRD Wyatt 36-23 well, Location #316142, in Rio Blanco County, Colorado. This location is within or in close proximity to Parks and Wildlife (CPW) with High Priority/NSO/Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal production operations the following compliance issues were observed:

1. API Numbers not displayed on tank battery sign.
2. Gas meter calibration card not visibly displayed.
3. Insufficient BMPs to control vehicle tracking.
4. Open end tank valve.
5. Soil staining at tank battery.
6. Chemical tank not in use.
7. Illegible chemical tank labels.
8. Chemical containments full of liquid.

Refer to attached photographs for Corrective Actions.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Chemical tank labels missing and/or illegible. Engine lube oil tank lacking label.		
Corrective Action:	Containers that are used to store, treat, or otherwise handle a hazardous material and which are required to be marked, placarded, or labeled in accordance with the U.S. Department of Transportation's Hazardous Materials Regulations, will retain the markings, placards, and labels on the Container. Such markings, placards, and labels will be retained on the Container until it is sufficiently cleaned of residue and purged of vapors to remove any potential hazards.		Date: <u>05/01/2023</u>
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Tank battery sign missing API Number of well associated with the tank battery.		
Corrective Action:	The Tank battery sign will be no less than 3 square feet and no more than 6 square feet, and will provide: Name of the Operator; Telephone number at which the Operator can be reached at all times; Telephone number for local emergency services (911 where available); The public road used to access the Tank battery site; Well name(s) and API number(s) associated with the Tank battery and the legal location of the Well(s); and Location, including the quarter/quarter section, of the Tank battery.		Date: <u>06/19/2023</u>

Emergency Contact Number:			
Comment:	<input type="text" value="(800) 288-0560 or 911"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Chemical tank on containment tub not hooked up.		
Corrective Action:	The storage, placement, or maintenance of equipment, vehicles, trailers, commercial products, chemicals, drums, totes, containers, materials, and all other supplies not necessary for use on an Oil and Gas Locations is prohibited.		Date: <u>05/05/2023</u>

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No <input type="text"/>			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	TANK BATTERY		
Comment:	Woven wire		
Corrective Action:		Date:	

Type	PUMP JACK		
Comment:	Livestock panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks in plastic containment. Containment full of liquid. Material Handling and Spill Prevention BMPs need implementation and maintenance.		
Corrective Action:	Drain and properly dispose of liquids. Provide proper BMPs for spill prevention, handling and maintenance of equipment.	Date:	04/25/2023
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Accessible with valve.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration card not visibly displayed.		
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times.	Date:	05/05/2023
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: FWKO	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	HEATED STEEL AST		
Comment:	Loadline and tank valves have plugs installed.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		

Comment:	<p style="color:blue;">Loadline has valve installed lacking a cap or plug.</p> <p style="color:blue;">Soil staining at backside tank valve.</p>	
Corrective Action:	<p>All loadline valves or tank valves that can be used as a loadline will be plugged or capped.</p> <p>Remove and properly dispose of stained soils.</p>	Date: <u>05/05/2023</u>

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 232230 Type: WELL API Number: 103-09901 Status: PR Insp. Status: PR

Producing Well

Comment: [Rod pump](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Gravel				
		Ditches				
				Material Handling And Spill Prevention	Fail	Containments full of liquid
Ditches						

Comment: Stormwater BMPs need implementation and maintenance. Insufficient BMPs to control vehicle tracking.

Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation.

Oil and gas operators shall implement and maintain vehicle tracking Best Management Practices (BMPs) to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action: Provide proper BMPs to prevent sediment migration from location and lease road.

Date: 05/05/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403378466	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6087613
702501161	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6087608