

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/01/2023

Submitted Date:

06/06/2023

Document Number:

709400213

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
WOLD, REED 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478086	SPILL OR RELEASE	CL	01/15/2021		-	UPRR 43 PAN AM G Consolidation #2	CL

General Comment:

This is an interium and stormwater inspcetion.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

Soil erosion blankets improperly installed or damaged by the stormwater runoff.

Corrective Action:

Comply with Rule 1002.f

Date: 06/01/2023

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Fail		Fail		Fail	No berm/ditch to prevent runoff from entering site
Blankets	Fail		Fail		Fail	Stabilization blankets damaged/Improper install

Comment: Soil erosion and large amount of sediment accumulation on site due to stormwater runoff flowing across location. No BMP's were installed to prevent stormwater from entering the location from the county road.

Corrective Action: **Comply with Rule 1002.F**
RUNOFF shall mean rain or snowmelt that flows over land and does not percolate into soil and includes stormwater that flows onto and off of an oil and gas location or facility.

Date: 06/01/2023

Pits: ☐ NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
-------	--------	---------	------	-------

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action: _____

Date: _____

Fencing:

Fencing Type: Safety Fencing Condition: Inadequate

Comment: _____

Corrective Action: _____

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective Action: _____

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
Per Rule 1002.f., oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004. Operators shall employ BMPs, as necessary to comply with this rule, at all oil and gas locations, including, but not limited to, well pads, soil stock piles, access roads, tank batteries, compressor stations, and pipeline rights of way. BMPs shall be selected based on site specific conditions, such as slope, vegetation cover, and proximity to water bodies, and may include maintaining in-place some or all of the BMPs installed during the construction phase of the facility. Where applicable based on site-specific conditions, operators shall implement BMPs in accordance with good engineering practices.	woldr	06/05/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403424678	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6137279
709400218	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6136697