

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NESW

Location #324154

Date: 6/19/2023



SW Corner of Location – Photo #04565

NW Corner of Location – Photo #04566

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NESW

Location #324154

Date: 6/19/2023



NE Corner of Location – Photo #04567

SE Corner of Location – Photo #04568

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NESW

Location #324154

Date: 6/19/2023



Wellhead – Photo #04569

Separators – Photo #04570

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NESW

Location #324154

Date: 6/19/2023



Tank Battery – Photo #04571

Access Road Lacks Stabilization – Photo #04575

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NESW

Location #324154

Date: 6/19/2023



Rill Erosion Across Access Road – Photo #04576

Rill Erosion Across Access Road – Photo #04577

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NESW

Location #324154

Date: 6/19/2023



Rill Erosion Across Access Road – Photo #04578

Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #04579