

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403352607

Date Received:

03/22/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10611

Name of Operator: LONGS PEAK RESOURCES LLC

Address: 2727 ALLEN PARKWAY SUITE 1850

City: HOUSTON State: TX Zip: 77019

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Brandi Terry

8327480912

brandi.terry@boomtownoil.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693701046

Inspection Date: 02/21/2023

FIR Submit Date: 02/22/2023

FIR Status: _____

Inspected Operator Information:

Company Name: LONGS PEAK RESOURCES LLC

Company Number: 10611

Address: 2727 ALLEN PARKWAY SUITE 1850

City: HOUSTON State: TX Zip: 77019

LOCATION - Location ID: 452516

Location Name: Oxnard East Number: 0607-8CH County: _____

Qtrqr: SESE Sec: 31 Twp: 12N Range: 66W Meridian: 6

Latitude: 40.958630 Longitude: -104.812780

FACILITY - API Number: 05-123- -00 Facility ID: 452516

Facility Name: Oxnard East Number: 0607-8CH

Qtrqr: SESE Sec: 31 Twp: 12N Range: 66W Meridian: 6

Latitude: 40.958630 Longitude: -104.812780

CORRECTIVE ACTIONS:

1 ☒ CA# 167661

Corrective Action: Cleanup spills, hand oily waste pursuant to Rule 905.e.; Repair and maintain separator pursuant to Rule 608.e.

Date: 03/22/2023

Response: CA COMPLETED

Date of Completion: 03/16/2023

Operator Comment: In the treater building, the sight glass tube was replaced. Everything was cleaned up and disposed of accordingly. Valves on the sight glass tube now stay closed unless opening for a couple minutes to check levels. The less time the valves are open, will in turn create less exposure to the risk of leaking or breaking for any reason.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 167662

Corrective Action: Cleanup spills, hand oily waste pursuant to Rule 905.e.; implement BMPs to prevent spills at AST loadouts

Date: 03/22/2023

Response: CA COMPLETED

Date of Completion: 03/16/2023

Operator Comment: For the load out lines, cleanliness of truckers has been the cause of this. Informed trucking companies of issue and corrective measures will be taken within there departments. The small drip spots were cleaned and disposed of accordingly.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brandi Terry

Signed: _____

Title: Regulatory Specialist

Date: 3/22/2023 9:09:35 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403352607	FIR RESOLUTION SUBMITTED
403352720	Pictures

Total Attach: 2 Files