

Storm Water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO PA 343-34 Pad

Location ID: 324217



Location Overview: Location is within High Priority/Density Habitat areas & Bald Eagle Nest/Roost Sites. Location is within Rule 411a Surface Water External Buffer.

Section/Township/Range: 34 6S95W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO PA 343-34 Pad
Location ID: 324217



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO PA 343-34 Pad
Location ID: 324217



Photo # 9477 Erosion & transport of sediment



Photo # 9478 Erosion & transport of sediment

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO PA 343-34 Pad
Location ID: 324217



Photo # 9484 Erosion & transport of sediment



Photo # 9485 Erosion & transport of sediment

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO PA 343-34 Pad
Location ID: 324217



Photo # 9481 Erosion & transport of sediment off location & into a vegetated area/insufficient BMP's



Photo # 9482 Erosion & transport of sediment off location & into a vegetated area/insufficient BMP's

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO PA 343-34 Pad

Location ID: 324217



Photo # 9486 Erosion & transport of sediment off location & into a vegetated area/insufficient BMP's



Photo # 9487 Erosion & transport of sediment off location & into a vegetated area/insufficient BMP's

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO PA 343-34 Pad

Location ID: 324217



Sep 18, 2023 at 9:52:15 AM
CO

Photo # 9488 Erosion & transport of sediment off location & into a vegetated area/insufficient BMP's



Sep 18, 2023 at 9:52:26 AM
CO

Photo # 9489 Erosion & transport of sediment off location & into a vegetated area/insufficient BMP's

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO PA 343-34 Pad

Location ID: 324217



Photo # 9497 Erosion & transport of sediment off location & into a vegetated area/insufficient BMP's



Photo # 9499 Erosion & transport of sediment off location & into a vegetated area/insufficient BMP's

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO PA 343-34 Pad

Location ID: 324217



Photo # 9500 Erosion & transport of sediment off location & into a vegetated area/insufficient BMP's



Photo # 9504 Erosion & transport of sediment off location & into a vegetated area/insufficient BMP's

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO PA 343-34 Pad

Location ID: 324217



Photo # Erosion & transport of sediment off location & into a vegetated area/insufficient BMP's