

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/12/2023

Submitted Date:

09/26/2023

Document Number:

696205272

FIELD INSPECTION FORMLoc ID 316789 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 9006

Name of Operator: BOOCO'S CONTRACT SERVICES INC

Address: P O BOX 572

City: HAYDEN State: CO Zip: 81639

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		boocosinc@aol.com	
Wolverton, Casey		casey.wolverton@state.co.us	
Maxwell, Logan		logan.maxwell@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287315	WELL	PA	09/30/2014	OW	107-06231	PELTIER 11-12	RI
316789	LOCATION	CL			-	PEILTIER 1-11H	RI

General Comment:

On 9/12/2023, Reclamation Specialists' Aaron Trujillo and Logan Maxwell conducted a Final Reclamation Inspection at Booco's Contract Service Inc's Peltier 11-12

This is a follow-up to inspection #692402573 dated 10/04/2020 to document compliance with the following corrective actions:
-Final Reclamation.

It was observed in this inspection that the Location remains out of compliance with ECMC Rules and Corrective actions.

The following new compliance issues were observed during this inspection:

- Stormwater
- Good Housekeeping

Refer to the "Location", "Reclamation" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable; The "Date of Discovery" is being provided as the corrective action date for all new observed compliance issues. Location will remain out of compliance until corrective action(s) has(have) been resolved and a follow up inspection will be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.

Date

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

TRASH

Comment:

It was observed in this inspection that various trash and debris were observed on the Location.

Corrective Action:

Comply with 606 Rules and removed trash/debris

Date: 09/12/2023

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	<u>287315</u>	Type:	<u>WELL</u>	API Number:	<u>107-06231</u>	Status:	<u>PA</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>316789</u>	Type:	<u>LOCATION</u>	API Number:	<u>-</u>	Status:	<u>CL</u>	Insp. Status:	<u>RI</u>

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: Non-cropland

Well plugged Pass Pit mouse/rat holes, cellars backfilled _____

Debris removed Fail No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed Fail

Location and associated production facilities reclaimed Fail Locations, facilities, roads, recontoured Fail

Compaction alleviation Fail Dust and erosion control Fail

Non cropland: Revegetated 80% Fail Cropland: perennial forage _____

Weeds present Fail Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: See "COGCC Comments" at the end of this report.

Corrective Action: _____ Date 11/16/2020

Conduct reclamation in accordance with the ECMC 1004 rules, including re-contouring, stabilizing slopes and installing appropriate BMPs to stabilize the location. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local soil conservation district. Comply with Rules 1004.e and 606.c and Control all Undesirable and Noxious Plant Species. Ongoing weed monitoring/management required until Location receives a passing final reclamation inspection.

Overall Final Reclamation

Fail

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: It was observed in this inspection that control measures to manage runoff in a manner that minimizes erosion, degradation and sediment transport are missing or insufficient; cut slopes lack stabilization and degradation is evident; gully erosion due to runoff also observed on the fill slopes.

Corrective Action: Immediately Comply with Rule 1002.f and install or repair required stormwater and erosion control measures. Temporary stormwater and erosion control BMPs will be required until Final Reclamation work is performed, at which point long term control measures will be required to stabilize the seeded soils, until long-term stabilization has been achieved. Continue to monitor and manage stormwater on Location until site receives a passing final reclamation inspection

Date: 09/12/2023

Pits: ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>RECLAMATION COMMENT</p> <p>Inspection #692402573 observed that the Location had not been reclaimed in accordance with 1004 Rules; specifically, anchor equipment has not been removed, gravel/road base has not been removed from the pad, compaction alleviation has not been performed, and the Location had not been recontoured/regraded and reclaimed. Inspection required Operator to comply with 1004 Rules.</p> <p>It was observed in this inspection that corrective actions to reclaim the Location have not been taken; Pad remains compacted and contains gravel; Location has not been recontoured/regraded and slopes lack stabilization (see stormwater); Anchor equipment and Operator sign have not been removed. Trash and ruderal weed debris are present across Location. Noxious weeds, Houndstongue and Canada thistle (List B) remain established on this site.</p>	trujilloam	09/26/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
403542275	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6264788
696205273	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6264783