

DE	ET	OE	ES
----	----	----	----

Document Number:
 403547785
 Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 46290 Contact Name: Lily Clark
 Name of Operator: KP KAUFFMAN COMPANY INC Phone: (303) 8254822
 Address: 1700 LINCOLN ST STE 4550 Fax: _____
 City: DENVER State: CO Zip: 80203 Email: lclark@kpk.com

For "Intent" 24 hour notice required, Name: Medina, Justin Tel: (720) 471-0006
COGCC contact: Email: justin.medina@state.co.us

Type of Well Abandonment Report: Notice of Intent to Abandon Subsequent Report of Abandonment

API Number 05-001-08732-00
 Well Name: RUEBEL ET AL Well Number: 1-3
 Location: QtrQtr: NWNW Section: 1 Township: 1S Range: 65W Meridian: 6
 County: ADAMS Federal, Indian or State Lease Number: _____
 Field Name: WATTENBERG Field Number: 90750

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.997830 Longitude: -104.617240
 GPS Data: GPS Quality Value: 2.0 Type of GPS Quality Value: _____ Date of Measurement: 06/10/2010
 Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other Offset frac agreement
 Casing to be pulled: Yes No Estimated Depth: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
D SAND	7759	7763			
J SAND	7819	7853			
Total: 2 zone(s)					

Casing History

(Empty area for Casing History)

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J-55	24	0	221	215	221	0	VISU
1ST	7+7/8	4+1/2	J-55	11.6	0	7940	375	7940	6047	CALC
S.C. 1.1						1186	280	1186	0	CALC

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7769 with 2 sacks cmt on top. CIBP #2: Depth 7709 with 2 sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 8 sks cmt from 6097 ft. to 5997 ft. Plug Type: CASING Plug Tagged:
 Set 15 sks cmt from 1332 ft. to 1136 ft. Plug Type: CASING Plug Tagged:
 Set 8 sks cmt from 678 ft. to 578 ft. Plug Type: CASING Plug Tagged:
 Set 25 sks cmt from 271 ft. to 0 ft. Plug Type: CASING Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at 4798 ft. with 32 sacks. Leave at least 100 ft. in casing 4748 CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Number of Days from Setting Surface Plug to Capping or Sealing the Well: _____
 Surface Plug Setting Date: _____ Cut and Cap Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 Yes No

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Lily Clark

Title: Prod & Ops Engineer Date: _____ Email: lclark@kpk.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: _____

COA Type	Description
0 COA	

Attachment List

Att Doc Num	Name
403547810	WELLBORE DIAGRAM
403547812	WELLBORE DIAGRAM

Total Attach: 2 Files

General Comments

User Group	Comment	Comment Date
		Stamp Upon Approval

Total: 0 comment(s)