

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/09/2023

Submitted Date:

10/12/2023

Document Number:

699107590

FIELD INSPECTION FORMLoc ID 310792 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 65110

Name of Operator: O'BRIEN ENERGY RESOURCES CORP

Address: 18 CONGRESS ST STE 207

City: PORTSMOUTH State: NH Zip: 03801

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Forma, Joseph	603-427-2099 x111	joeforma@obenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297036	WELL	TA	07/29/2020	GW	123-26982	LOST CREEK 45	TA

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Overgrown vegetation around the well needs to be removed for good housekeeping. See attached photo		
Corrective Action:	Comply with Rule 606.		Date: 10/25/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 297036 Type: WELL API Number: 123-26982 Status: TA Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: T/A

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 11/27/2021 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: No updated annual BH test on file. Submit reports. Form 17 #403257247 indicates it was last tested on 12/9/20. 11/14/2023

Corrective Action: Submit reports as per Rule 419. Date: _____

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Monday 10/9/23 at approximately 1138hrs I, Inspector Adam Burns, Conducted an on-site inspection at Lost Creek 45 of O'Brien Energy Resources Corp. API #05-123-26982 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Overgrown vegetation around the well needs to be removed for good housekeeping.</p> <p>Comply with Rule 606. With a Corrective Action date of 10/25/23</p> <p>No updated annual BH test on file. Submit reports. Form 17 #403257247 indicates it was last tested on 12/9/20. Submit reports as per Rule 419. With a Corrective Action date of 11/14/23</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p>	burnsa	10/12/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403558963	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6282655
699107591	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6282624