

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/24/2023

Submitted Date:

10/27/2023

Document Number:

709100148**FIELD INSPECTION FORM**Loc ID 317498 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 76840Name of Operator: SCHNEIDER ENERGY SERVICES INCAddress: P O BOX 889City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Krystal Heibel		krystal.heibel@state.co.us	
Bothwell, Kevin	(970) 867-9437	kbothwell@rivalservices.net	All Inspections
CAMP, LEWIS		lewis@schneiderenergy.com	SCHNEIDER OPERATIONS
SCHNEIDER, JEFF	970-867-9437	jeff@schneiderenergy.com	Principal Agent

General Comment:

On October 24, 2023, ECMC Environmental Unit Staff Krystal Heibel inspected the April location (Location ID: 317498).

This site has an active Remediation Project.

Remediation #21609: Pit Closure of the April 12-14 pit (most recent Form 27 Supplemental received April 22, 2022)

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Sign not posted or information inaccurate at battery. Sign indicated that this is the Dryer #1 location.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	11/28/2023

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on site.		
Corrective Action:	Comply with Rule 606	Date:	11/13/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Other	#		corrective date
Comment:	Secondary containment is inadequate to contain 150% of the volume of the largest tank. See photo documentation.		
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o. Location will remain out of compliance until the corrective action has been resolved.		Date: 11/28/2023
Type: Other	#		
Comment:	Wildlife protections devices around the pit are not adequate. Unauthorized discharge of E&P Waste from multiple pipe openings located near the pit. See photos attached for reference.		
Corrective Action:	Install or repair wildlife protection equipment. Prevent any unauthorized discharge.		Date: 11/06/2023

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Inspector Name: Heibel, Krystal

Document Num	Description	URL
403575463	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6300786
709100149	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6300780