




00053459

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. _____
Unit _____



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 30, 19 65

Well No. 1 Banker is located 650 ft. from $\begin{Bmatrix} N \\ S \end{Bmatrix}$ line and 400 ft. from $\begin{Bmatrix} E \\ W \end{Bmatrix}$ line of sec. 12


$\frac{1}{4}$ Sec. and Sec. No. 12 N 103 W 6th
(Twp.) (Range) (Meridian)
Rangely Field Rio Blanco Colorado
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Bridged hole @ 100'. w/ rocks. Filled top 100' w/ cement and erected marker. Plugged and abandoned.



DVR	
WRS	
HHM	
JAM	
FJP	✓
JJD	✓

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company U.S. Development Corp. plugged by Colo. Well Service, Inc.

Address _____ Box 743, Rangely, Colo.

Approved DEC 13 1965 By *H.B. Diller*

Mr. Rogers, Director Title V. Pres.