

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/05/2023

Submitted Date:

12/06/2023

Document Number:

696205438

## FIELD INSPECTION FORM

 Loc ID 322539 Inspector Name: Trujillo, Aaron On-Site Inspection  2A Doc Num:
**Operator Information:**
 OGCC Operator Number: 96850  
 Name of Operator: TEP ROCKY MOUNTAIN LLC  
 Address: 1058 COUNTY ROAD 215  
 City: PARACHUTE State: CO Zip: 81635
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 2 Number of Comments  
 1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
322539	LOCATION	AC	09/11/2023		-	Arco Deep 1-27	CI

**General Comment:**

On 12/5/2023, Reclamation Specialist Trujillo attempted to conduct a follow-up stormwater and construction inspection at TEP Rocky Mountain's Arco Deep/1-27 location in Garfield County, Colorado.

ECMC Staff was unable to access Location due to snow conditions.

Any corrective action(s) from previous inspections that have not been addressed are still applicable; The "Date of Discovery" is being provided as the corrective action date for all new observed compliance issues. Location will remain out of compliance until corrective action(s) has(have) been resolved and a follow up inspection will be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Location not accessible during normal business hours; snow maintenance along road has not been conducted. ECMC Staff was unable to access Location.		
Corrective Action:	Repair and maintain lease road to comply with rule 204.	Date:	12/05/2023

Overall Good:

<b>Emergency Contact Number:</b>	
Comment:	<input style="width: 90%;" type="text"/>
Corrective Action:	<input style="width: 90%;" type="text"/>
Date:	_____

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Venting:</b>			
Yes/No			
Comment:	<input style="width: 90%;" type="text"/>		
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:	<input style="width: 90%;" type="text"/>		
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 322539 Type: LOCATION API Number: - Status: AC Insp. Status: CI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403616949	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6347877">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6347877</a>
696205439	Access Road	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6347814">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6347814</a>