

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/14/2023

Submitted Date:

12/17/2023

Document Number:

708902548**FIELD INSPECTION FORM**Loc ID 417582 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456931	Domestic Tap	AC	08/28/2018		-	Domestic Tap RWF 13-31	AC

General Comment:**CECMC Inspection Report Summary**

On 12/14/2023 at approximately 13:28 hours, I, Compliance Specialist, Wayne Smelser
Conducted a domestic tap inspection at TEP ROCKY MOUNTAIN LLC Domestic Tap RWF13-31
Location # 417582 Facility # 456931 in Garfield County Colorado.
While there, I observed the domestic tap is derived from TEP sales line.

This is a summary of inspection report

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Domestic tap - pipe rail fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 1		
Comment:	Domestic tap		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	456931	Type:	Domestic Tap	API Number:	-	Status:	AC	Insp. Status:	AC
Producing Well									
Comment:	While there, I observed the domestic tap is derived from TEP's sales line. The pressure is regulated by a big Joe regulator. Following regulator there's a fluid knock out equipped with a PRV, following the knock out there's a little Joe regulator & after the regulator there's an in line odorizer. Fittings appear to be adequate to handle the maximum operating pressures of the regulators.								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Domestic tap inspection only](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Domestic tap inspection only	smelserw	12/17/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708902549	Inspection 708902548 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6359149