

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403633286

Date Received:
12/21/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

8 of 8 CAs from the FIR responded to on this Form

8 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10797

Name of Operator: DESERT EAGLE OPERATING LLC

Address: 17101 PRESTON RD SUITE 105

City: DALLAS State: TX Zip: 75248

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Sanchez, Chris</u>		<u>chris.sanchez@state.co.us</u>
<u>Beardslee, Tom</u>		<u>tom.beardslee@state.co.us</u>
<u>Butler, Brad</u>	<u>972-345-9195</u>	<u>butleroil@yahoo.com</u>
<u>Costa, Ryan</u>		<u>ryan.costa@state.co.us</u>
<u>Bulf, Cathy</u>		<u>cathybulf@gmail.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 713600414

Inspection Date: 11/21/2023

FIR Submit Date: 11/22/2023

FIR Status: _____

Inspected Operator Information:

Company Name: DESERT EAGLE OPERATING LLC

Company Number: 10797

Address: 17101 PRESTON RD SUITE 105

City: DALLAS State: TX Zip: 75248

LOCATION - Location ID: 484360

Location Name: Red Rocks Number: 35-11 County: LAS ANIMAS

Qtrqtr: SENW Sec: 35 Twp: 29S Range: 55W Meridian: 6

Latitude: 37.475295 Longitude: -103.546960

FACILITY - API Number: 05-071-

-00

Facility ID: 484675

Facility Name: Red Rocks Number: 35-11

Qtrqtr: SENW Sec: 35 Twp: 29S Range: 55W Meridian: 6

Latitude: 37.475295 Longitude: -103.546960

CORRECTIVE ACTIONS:

1 CA# 188482

Corrective Action: Comply with Rule 608. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 11/21/2023

Response: CA COMPLETED

Date of Completion: 11/21/2023

Operator Comment: Valves, pipes, fittings, and producton facilities were checked and securely fastened Rule 608.e.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 188483

Corrective Action: Comply with Rule 606.

Date: 11/21/2023

Response: CA COMPLETED

Date of Completion: 11/27/2023

Operator Comment: Tree debris has been removed from the flowline and location - Rule 606

COGCC Decision: _____

COGCC Representative: _____

3 CA# 188484

Corrective Action: Comply with Rule 606.

Date: 11/21/2023

Response: CA COMPLETED

Date of Completion: 11/27/2023

Operator Comment: Trash and debris has been removed. Rule 606

COGCC Decision: _____

COGCC Representative: _____

4 CA# 188485

Corrective Action: Comply with 1002. b rules for soil removal and segregation.
Comply with 1002.c rules for protection of soils.

Date: _____

Response: CA COMPLETED

Date of Completion: 12/08/2023

Operator Comment: Rocks have been removed from the location. Soil has been replaced in the excavated areas and additional topsoil was added last. Areas of impacted soil were cleaned and properly disposed.
Rule 1002.b and Rule 1002.d.

COGCC Decision: _____

COGCC Representative: _____

5 CA# 188486

Corrective Action: Operator shall abide by the reclamation rules to minimize surface disturbances per the 1002e rule.

Date: 11/21/2023

Response: CA COMPLETED

Date of Completion: 11/21/2023

Operator Comment: Operator's personnel have reviewed Rule 1002.e. and been directed to stay on access road boundaries.

COGCC Decision: _____

COGCC
Representative:

6 CA# 188487

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: 11/21/2023

Response: CA COMPLETED

Date of Completion: 12/01/2023

Operator
Comment: Wattles have been replaced and repaired. Rule 1002.f.(2)

COGCC Decision:

COGCC
Representative:

7 CA# 188488

Corrective Action: Comply with Rule 905. for Management of E&P Waste. Clean up and contain.

Date: _____

Response: CA COMPLETED

Date of Completion: 12/08/2023

Operator
Comment: Drill cuttings and contaminated soil has been cleaned up and properly disposed. Rule 905.

COGCC Decision:

COGCC
Representative:

8 CA# 188489

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)
Immediate clean up of spilled material.
Implement or modify BMPs for improved material handling and spill prevention.

Date: 11/21/2023

Response: CA COMPLETED

Date of Completion: 12/27/2023

Operator
Comment: BMP's have been repaired per Rule 1002.f.(2). The torn concrete bag has been removed. Oil stained soil has been cleaned up and properly disposed. The cuttings pile has been controlled and placed on the bermed liner. Perimeter BMPs have been repaired. Field personnel have been advised about concerns of vehicle tracking from the dirt access road to the dirt County Road and will take necessary measure to reduce the concerns,

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA 188482 completed immediately. CA 188483 and 188484 complete, attached photo RR 35-11 FIRR 403612782 Photos.pdf; CA 188485 complete, attached photo RR 35-11 Wellhead Photo.pdf and RR 35-11 Location Reclamation.pdf; CA 188487 complete, attached photo RR 35-11 Wattle Repair and Flowline Reclamation.pdf; CA 188488 complete, attached photo Tickets for 35-11.pdf

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cathy Bulf

Signed: _____

Title: Manager

Date: 12/21/2023 11:13:57 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403633406	Flowline Trench at Wellhead Reclamation
403633408	Tree Debris and Trash Removed at Location
403633413	Impacted and Contaminated Soil Disposal Manifesto and Landfill Receipt
403633462	RR 35-11 Rocks Removed and Location Reclamation
403633465	Wattle Repair and Flowline Reclamation

Total Attach: 5 Files