

TEP Rocky Mountain LLC  
Goldsborough PA 22-11  
Loc ID: 414939



**Lack of compaction accessing wellheads**




**Lack of compaction around wellheads**



TEP Rocky Mountain LLC  
Goldsborough PA 22-11  
Loc ID: 414939



Lack of compaction around wellheads



Sign at tank battery

