

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/11/2023

Submitted Date:

12/21/2023

Document Number:

714300006

FIELD INSPECTION FORM

Loc ID 467175 Inspector Name: Brown, Kari On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
Graber, Nikki		nikki.graber@state.co.us	
Peterson, John		jpeter@kpk.com	KPK environmental
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
476532	SPILL OR RELEASE	CL	10/27/2020		-	HORST-SCHUTT PW Storage Vessel	EI

General Comment:

[This is an environmental inspection to determine the status of the remedial excavation of Spill ID 476532/Remediation Project No 14115.](#)

[All corrective actions from previous inspections that have not been addressed are still applicable.](#)

[There were no operator or contract environmental personnel on location at the time of this field inspection.](#)

[Photos attached to document site conditions.](#)

Inspected Facilities

Facility ID: 476532 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Remediation excavation remains open. Excavation backfill was approved 11/16/2023 to address the ongoing threat to public health and safety at this location (document no 1561587).

Corrective Action: Operator shall provide 48 hour notice to area EPS and Nikki Graber (nikki.graber@state.co.us) prior to backfill.

Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403634308	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6368869
714300007	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6368862