

FORM  
6Rev  
12/05State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

400289814

Date Received:

05/29/2012

## WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10341

Contact Name: Karen LeBaron

Name of Operator: PUCKETT LAND COMPANY

Phone: (303) 763-1000

Address: 5460 S. QUEBEC STREET - STE #250

Fax: (303) 763-1040

City: GREENWOOD State: CO Zip: 80111

Email: klebaron@puckettland.com

For "Intent" 24 hour notice required, Name: LONGWORTH, MIKE Tel: (970) 812-7644

COGCC contact: Email: mike.longworth@state.co.us

API Number 05-103-10930-00

Well Name: FIGURE FOUR RANCH

Well Number: 499-12-48

Location: QtrQtr: SESW Section: 12 Township: 4S Range: 99W Meridian: 6

County: RIO BLANCO

Federal, Indian or State Lease Number:

Field Name: WILDCAT

Field Number: 99999

☒ Notice of Intent to Abandon☐ Subsequent Report of Abandonment

## Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.709764 Longitude: -108.453694

GPS Data:

Date of Measurement: 07/30/2008 PDOP Reading: 2.5 GPS Instrument Operator's Name: ROBERT L. KAY

Reason for Abandonment: ☐ Dry ☐ Production for Sub-economic ☐ Mechanical Problems☒ Other Order of COGCCCasing to be pulled: ☒ Yes ☐ No Top of Casing Cement: 2440Fish in Hole: ☐ Yes ☒ No If yes, explain details belowWellbore has Uncemented Casing leaks: ☐ Yes ☒ No If yes, explain details below

Details:

## Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
COZZETTE-CORCORAN	7842	7934			
MANCOS B	9732	9962			

Total: 2 zone(s)

## Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
CONDUCTOR	24	20		80	220	80	0	VISU
SURF	14+3/4	9+5/8	36	2,390	2,483	2,390	0	CALC
1ST	8+3/4	5+1/2	17	11,003	1,383	11,003	6,232	CBL

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 9682 with 25 sacks cmt on top. CIPB #2: Depth 7790 with 25 sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIPB #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 20 sks cmt from 7000 ft. to 6824 ft. Plug Type: CASING Plug Tagged: ☐  
Set 40 sks cmt from 880 ft. to 780 ft. Plug Type: CASING Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 80 sacks half in. half out surface casing from 2340 ft. to 2490 ft. Plug Tagged: ☒

Set 40 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing Plugging Date: \_\_\_\_\_

\*Wireline Contractor: \_\_\_\_\_ \*Cementing Contractor: \_\_\_\_\_

Type of Cement and Additives Used: \_\_\_\_\_

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No \*ATTACH JOB SUMMARY

Technical Detail/Comments:

DV tool @ 6983', 20 sacks cement plug across DV tool. Also DV @ 830'.

Work to begin week of 6/12. Well ordered plugged by the COGCC - Order 1V-378

PLC would appreciate your help with processing and approval of this application.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Karen LeBaron

Title: Petroleum Landman Date: 5/29/2012 Email: klebaron@puckettland.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: KRABACHER, JAY Date: 5/31/2012

**CONDITIONS OF APPROVAL, IF ANY:** \_\_\_\_\_ Expiration Date: 11/29/2012

### **Attachment Check List**

Att Doc Num	Name
400289814	FORM 6 INTENT SUBMITTED
400289853	WELLBORE DIAGRAM

Total Attach: 2 Files

### **General Comments**

<b><u>User Group</u></b>	<b><u>Comment</u></b>	<b><u>Comment Date</u></b>
Engineer	OPR did not note nor include DV @ 830'. will add balanced plug across the DV interval.	5/31/2012 4:40:29 PM
Permit	Both WBD's included in attachment with plugging procedure.	5/30/2012 6:53:03 AM

Total: 2 comment(s)