



DE ET OE ES

Document Number:
400506294

Date Received:
11/01/2013

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.
 A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 47120 Contact Name: CHERYL LIGHT
 Name of Operator: KERR-MCGEE OIL & GAS ONSHORE LP Phone: (720) 929-6461
 Address: P O BOX 173779 Fax: (720) 929-7461
 City: DENVER State: CO Zip: 80217- Email: CHERYL.LIGHT@ANADARKO.COM

For "Intent" 24 hour notice required, Name: JOHNSON, RANDELL Tel: _____
 Email: randell.johnson@state.co.us

COGCC contact: _____

API Number 05-123-09725-00 Well Number: 2
 Well Name: ARISTOCRAT 32-9
 Location: QtrQtr: SWNE Section: 9 Township: 3N Range: 65W Meridian: 6
 County: WELD Federal, Indian or State Lease Number: _____
 Field Name: ARISTOCRAT Field Number: 2925

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.241420 Longitude: -104.666050
 GPS Data:
 Date of Measurement: 06/13/2006 PDOP Reading: 2.5 GPS Instrument Operator's Name: Steve Fisher
 Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other _____
 Casing to be pulled: Yes No Estimated Depth: 900
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
SUSSEX	4475	4538			

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	442	300	442	0	VISU
1ST	7+7/8	5+1/2	15.5	4,618	250	4,618	3,000	CALC

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 4415 with 25 sacks cmt on top. CIPB #2: Depth 100 with 30 sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIPB #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 25 sks cmt from 4415 ft. to 4210 ft. Plug Type: CASING Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set 165 sacks half in. half out surface casing from 1000 ft. to 240 ft. Plug Tagged:
 Set 30 sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____
 *Wireline Contractor: _____ *Cementing Contractor: _____
 Type of Cement and Additives Used: _____
 Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: CHERYL LIGHT
 Title: SR. REGULATORY ANALYST Date: 11/1/2013 Email: DJREGULATORY@ANADARKO.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: JENKINS, STEVE Date: 11/6/2013

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: 5/5/2014

COA Type

Description

	NOTE: Change in plugging procedure 1) Provide 24 hour notice of MIRU to Jim Precup at 303-726-3822 or e-mail at James.Precup@state.co.us. 2) For 1000' plug: pump plug and displace, if not circulated to surface - shut-in, WOC 4 hours and tag plug (must be 240' or shallower). Leave at least 100' cement in the casing for each plug. 3) Properly abandon flowlines as per Rule 1103.
--	---

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
400506294	FORM 6 INTENT SUBMITTED
400506295	PROPOSED PLUGGING PROCEDURE
400506296	WELLBORE DIAGRAM
400506297	WELLBORE DIAGRAM

Total Attach: 4 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	LOCATION: SW 1/4 OF NE 1/4 OF SEC. 9, TOWNSHIP 3N, RANGE 65W (1650FSL, 1650 FEL) GROUND ELEVATON 4802' DEEPEST WATER WELL WITHIN 1 MILE IS 55', BOTTOM OF THE FOX HILLS AT THE WELL SITE: 503', TOP 177'.	11/6/2013 9:33:10 AM

Total: 1 comment(s)